

Washing, Care and Cleaning

The increasingly generalised utilisation of washing machines in the household field and the recourse to laundry and dry cleaning services demand continuous cautions, even after the finalisation of the manufacturing process.

Washing

The use of various conditions in temperature, shaking and several solvents implies a precious advice.



Do not wash.
Be careful when washing the articles in the wet state.



The article can be washed by machine or hand.
The numbers indicated inside the washing tub show the maximum washing temperature in degrees Celsius.



Only hand wash.
Do not wash by machine.
A maximum temperature of 40°C.
Handle carefully.



A maximum temperature of 95°C.
Normal mechanical action.
Normal rinsing.
Normal spinning.



A maximum temperature of 95°C.
Reduced mechanical action.
Rinsing with a gradual decrease of the temperature (cooling)
Reduced spinning.



A maximum temperature of 60°C.
Normal mechanical action.
Normal rinsing.
Normal spinning.



A maximum temperature of 60°C.
Reduced mechanical action.
Rinsing with a gradual decrease of the temperature (cooling)
Reduced spinning.



A maximum temperature of 40°C.
Normal mechanical action.
Normal rinsing.
Normal spinning.



A maximum temperature of 40°C.
Reduced mechanical action.
Rinsing with a gradual decrease of the temperature (cooling)
Reduced spinning.



A maximum temperature of 40°C.
A much reduced mechanical action.
Rinsing with a gradual decrease of the temperature (cooling)
Reduced spinning.
Do not wring out.

Bleaching



Chlorine bleaching.
(Bleaches)



It's not permitted treatment
with chlorine products.
Be careful when washing in
the wet stage.



It's permitted chlorine bleaching.
Only in cold wash and with a diluted
solution.

Artificial drying



Drying in the machine after the
washing.



It is possible to carry out the drying in a
rotating drum.
Normal drying cycle with a mild
temperature.



It is possible to carry out the
drying in a rotating drum.
Normal drying cycle without
temperature restrictions.



Tumble drying is not permitted.

Natural Drying



The vertical drying is possible.



The vertical drying is possible without
wringing.



Horizontal drying.

Ironing



Do not iron.
Steaming and any steam
treatments are not permitted.



Ironing at maximum sole plate
temperature of 200°C.



Ironing at maximum sole plate
temperature of 110°C.
The steam treatment can be
risky.



Ironing at maximum sole plate
temperature of 150°C.

Cleaning



Dry cleaning.



Dry cleaning with all solvents
normally used for the dry cleaning.



Dry cleaning with all solvents,
except for trichloroethylene.
Normal cleaning procedures with
no restrictions.



Dry cleaning with all solvents, except for trichloroethylene.
Restrictions in the water addition and/or in the mechanical
action and/or in the temperature, during the cleaning
and/or the drying.



Dry cleaning with
trifluorotrichloroethylene
(distillation temperature between
150°C and 201°C, flammability point
between 38°C to 60°C).



Dry cleaning with solvents indicated in the F symbol.
Restrictions in the water addition and/or in the
mechanical action and/or in the temperature, during
the cleaning and/or the drying.



Do not dry-clean.
Do not remove stains with